

Storm Water Management and Erosion control
Location Name: TEP Rocky Mountain LLC CLOUGH 101 Pad
Location # 322405



**Location Overview: Location is within High Priority/Density
Habitat areas.**

Section/Township/Range: 15 6S94W

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC CLOUGH 101 Pad
Location # 322405



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC CLOUGH 101 Pad
Location # 322405



Photo # 8261 Degradation, erosion & transport of sediment on lease road



Photo # 8262 Degradation, erosion & transport of sediment on lease road

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC CLOUGH 101 Pad
Location # 322405



Photo # 8263 Degradation, erosion & transport of sediment on lease road



Photo # 8264 Degradation, erosion & transport of sediment on lease road

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC CLOUGH 101 Pad
Location # 322405



Photo # 8265 Degradation, erosion & transport of sediment on lease road



Photo # 8266 Degradation, erosion & transport of sediment on lease road

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC CLOUGH 101 Pad
Location # 322405



Photo # 8267 Degradation, erosion & transport of sediment on lease road



Photo # 8268 Degradation, erosion & transport of sediment on lease road

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC CLOUGH 101 Pad
Location # 322405



Photo # 8269 Erosion & transport of sediment on lease road



Photo # 8270 Erosion & transport of sediment on lease road

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC CLOUGH 101 Pad
Location # 322405



**Photo # 8271 Erosion & transport of sediment on lease road
& going off lease road & down slope**



**Photo # 8272 Erosion & transport of sediment on lease road
& going off lease road & starting to go down slope**

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC CLOUGH 101 Pad
Location # 322405



**Photo # 8273 Erosion & transport of sediment on lease road
& going off lease road & down slope**



**Photo # 8274 Erosion & transport of sediment off lease road
& going down slope**

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC CLOUGH 101 Pad
Location # 322405



**Photo # 8275 Erosion & transport of sediment off lease road
& going down slope**



**Photo # 8276 Erosion & transport of sediment off lease road
& going down slope**

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC CLOUGH 101 Pad
Location # 322405



**Approximate location of road degradation, erosion
& transport of sediment highlighted in yellow.**



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC CLOUGH 101 Pad
Location # 322405



Approximate location of 2nd area with erosion & transport of sediment on lease road marked in red & yellow.

