

# Inspection Photos

12/05/2023

**Operator:** CAERUS PICEANCE LLC #10456

**Location ID:** 445862

**Inspection Doc:** 696205432

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 445862



**Photo 1:** Photos 1-2 taken from southern working pad surface. Photos provide an overview of the Location from east, southeast, southwest to west.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 445862



**Photo 2:** See comments under photo 2.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 445862



**Photo 3:** Tank battery facility. Signage not posted per 605.e



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 445862



**Photo 4:** Photos examples showing tanks lack caps/plugs



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 445862



**Photo 5:** Hose stored on working pad surface outside of containment. Fluids within hose apparent.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources