


Inspection Photos  
Location Name: UPRR #X13-06  
Location ID: 421536



Energy & Carbon Management Commission  
40.14575, -104.61939, 1467.8m, 139°  
Dec 5, 2023 12:03:00

Photo 1: location



Energy & Carbon Management Commission  
40.14555, -104.61922, 1470.2m, 237°  
Dec 5, 2023 12:03:20

Photo 2: Tank Battery Sign



Inspection Photos  
Location Name: UPRR #X13-06  
Location ID: 421536



Energy & Carbon Management Commission  
40.14558, -104.61929, 1463.0m, 148°  
Dec 5, 2023 12:04:06

Photo 3: Centralized tank battery



Energy & Carbon Management Commission  
40.14559, -104.61916, 1464.5m, 90°  
Dec 5, 2023 12:04:23

Photo 4: Equipment





Inspection Photos  
Location Name: UPRR #X13-06  
Location ID: 421536



Photo 5: Wellhead Sign, Operator Name no longer visible



Photo 6: TA wellhead