

Operator: CRESTONE PEAK RESOURCES
Location Name: GRANDE 4-65 20-19 1AH
Loc ID: 472938
Inspection: 709400639



Exhibit A

CA: Failure to control and manage undesirable plant species (Long spine sandbur) to prevent the spread of seeds onto adjacent lands. Mowing is not a sufficient management control for this species. Comply with rule 1003.

CA Resolution: Undesirable plant species have been controlled to prevent the spread of seeds onto adjacent lands to comply with Rule 1003.