

Ihnen 1A Photo Log  
December 1, 2023

**Title:**

Fencing fully surrounds the entire excavation.



**Title:**

Fencing fully surrounds the entire excavation.





**Title:**

Fencing fully surrounds the entire excavation.



**Title:**

Valves securely fastened on horizontal heater treater.





<b>Title:</b>	Unused equipment removed near wellhead.
---------------	---

<b>Title:</b>	Unused equipment removed near wellhead.
---------------	---

