

Inspection Photos
Location Name: State Pronghorn 14-2 PAD
Location ID: 435952



Photo 1 – Wellheads



Photo 2 – Wellheads

Inspection Photos
Location Name: State Pronghorn 14-2 PAD
Location ID: 435952



Photo 3 – Instrumental Air Unit



Photo 4 – Pig Station

Inspection Photos
Location Name: State Pronghorn 14-2 PAD
Location ID: 435952



Photo 5 – Tank Battery




Photo 6 – Capacity Labels

Inspection Photos
Location Name: State Pronghorn 14-2 PAD
Location ID: 435952



Photo 7 – Tank Battery Signs



Photo 8 – Tank Battery Signs

Inspection Photos
Location Name: State Pronghorn 14-2 PAD
Location ID: 435952



Photo 9 – Tank Battery Signs



Photo 10 – Tank Battery Signs

Inspection Photos
Location Name: State Pronghorn 14-2 PAD
Location ID: 435952



Photo 11 – NFPA Labels on 1339 and 1338 Tanks



Photo 12 – Tank Battery

Inspection Photos
Location Name: State Pronghorn 14-2 PAD
Location ID: 435952




Photo 13 – 1" Riser not OOSLAT



Photo 14 – ECDs

Inspection Photos
Location Name: State Pronghorn 14-2 PAD
Location ID: 435952



Photo 15 – Separators and Instrumental Air Unit



Photo 16 – Separators

Inspection Photos
Location Name: State Pronghorn 14-2 PAD
Location ID: 435952



Photo 17 – Line Heater and Gas Lift Injection Meter Houses



Photo 18 – Separators

Inspection Photos
Location Name: State Pronghorn 14-2 PAD
Location ID: 435952



Energy and Carbon Management Commission
40.42362, -104.29699, 4591.7ft
12/05/2023 13:38:53

Photo 19 – Signs at Entrance

