

Inspection Photos
Location Name: State Pronghorn 31-11HZ
Location ID: 423035



Photo 1 – Pumping Unit



Photo 2 – Stained Soil at Gas Engine

Inspection Photos
Location Name: State Pronghorn 31-11HZ
Location ID: 423035



Photo 3 – Wellhead



Photo 4 – Separator and ECD



Inspection Photos
Location Name: State Pronghorn 31-11HZ
Location ID: 423035



Photo 5 – Riser no OOSLAT



Photo 6 – Tank Battery

Inspection Photos
Location Name: State Pronghorn 31-11HZ
Location ID: 423035



Photo 7 – Tank Battery Signs




Photo 8 – Capacity Labels



Inspection Photos
Location Name: State Pronghorn 31-11HZ
Location ID: 423035



Photo 9 – Capacity and Content Labels




Photo 10 – 1" Risers not OOSLAT

