

Interim and Stormwater Inspection

November 14, 2023

Operator: Goodwin Energy Management LLC- #10395

Location ID: 320342

Inspection Document #: 709400662

Adams County, CO

SWNW Section 27 T1S R64W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Satterfield #1 & Tank Battery
Facility ID: 320342

Nov 14, 2023 at 11:07:34 AM
Hudson CO 80642
United States



Photo 1. Photo taken of location sign on site.

Nov 14, 2023 at 11:09:42 AM
Hudson CO 80642
United States



Photo 2. Photo taken of wellhead. Photo taken facing east.

Inspection Photos
Location Name: Satterfield #1 & Tank Battery
Facility ID: 320342

Nov 14, 2023 at 11:09:19 AM
Hudson CO 80642
United States



Photo 3. Photo taken of vegetation and weed debris (kochia) around wellhead. Photo taken facing east.

Nov 14, 2023 at 11:10:00 AM
Hudson CO 80642
United States



Photo 4. Photo taken of weeds (Kochia) between wellhead and tank battery. Photo taken facing west.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 709400666

Inspection Photos
Location Name: Satterfield #1 & Tank Battery
Facility ID: 320342

Nov 14, 2023 at 11:07:44 AM
Hudson CO 80642
United States



Photo 5. Photo taken of tank battery. Photo taken facing west.

Nov 14, 2023 at 11:08:06 AM
Hudson CO 80642
United States



Photo 6. Photo of stormwater erosion on access road and around tank battery . Photo taken facing southwest.

Inspection Photos

Location Name: Satterfield #1 & Tank Battery

Facility ID: 320342

Nov 14, 2023 at 11:08:13 AM
Hudson CO 80642
United States



Photo 7. Photo taken of stormwater erosion around tank battery. Photo taken facing south.

Nov 14, 2023 at 11:08:38 AM
Hudson CO 80642
United States



Photo 8. Photo taken of erosion from stormwater from access road across location. Photo taken facing northeast.

Inspection Photos

Location Name: Satterfield #1 & Tank Battery

Facility ID: 320342

Nov 14, 2023 at 11:08:53 AM
Hudson CO 80642
United States



Photo 9. Photo taken of erosion from stormwater from access road across location. Photo taken facing northeast.

Nov 14, 2023 at 11:08:55 AM
Hudson CO 80642
United States



Photo 10. Photo taken of unmarked risers on location. Photo taken facing east.