

# Interim and Stormwater Inspection

November 14, 2023

Operator: Smith Oil Properties LLC- #79905

Location ID: 320210

Inspection Document #: 709400670

Adams County, CO

SENE Section 18 T1S R64W

Reed Wold  
Reclamation Specialist, COGCC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Laurdison 42-18 & Tank  
Battery  
Facility ID: 320210

Nov 14, 2023 at 11:55:46 AM



**Photo 1.** Photo taken of location sign on site.

Nov 14, 2023 at 11:57:53 AM



**Photo 2.** Photo taken of wellhead. Photo taken facing southwest.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Number: 709400670



Inspection Photos  
Location Name: Laurdison 42-18 & Tank  
Battery  
Facility ID: 320210

Nov 14, 2023 at 11:57:56 AM



**Photo 3.** Photo taken of mowed vegetation around wellhead.  
Photo taken facing east.

Nov 14, 2023 at 11:57:59 AM



**Photo 4.** Photo taken of mowed vegetation around wellhead.  
Photo taken facing west.



Inspection Photos  
Location Name: Laurdison 42-18 & Tank  
Battery  
Facility ID: 320210

Nov 14, 2023 at 11:55:57 AM



**Photo 5.** Photo taken of tank battery. Photo taken facing west.

Nov 14, 2023 at 11:56:11 AM



**Photo 6.** Photo of weeds around tank battery . Photo taken facing southwest.



# Inspection Photos

Location Name: Laurdison 42-18 & Tank

Battery

Facility ID: 320210

Nov 14, 2023 at 11:56:56 AM



**Photo 7.** Photo taken of weeds (kochia & russian thistle) around separator. Photo taken facing southwest.

Nov 14, 2023 at 11:57:10 AM

34350 E 152nd Ave

Hudson CO 80603

United States



**Photo 8.** Photo taken of weeds (kochia & russian thistle) around separator. Photo taken facing north.