


Operator: CRESTONE PEAK RESOURCES
Location Name: State La Plata 5-65 13-15 4AH
Loc ID: 437846
Inspection: 709400647




☀ 255°SW (T) • 39.613481, -104.616349 ±3 m ▲ 1781 m



State LaPlata
06 Dec 2023, 8:44:14 AM

Exhibit A




☉ 224°SW (T) • 39.613325, -104.617026 ±6 m ▲ 1783 m



State LaPlata
06 Dec 2023, 8:45:00 AM

Exhibit B



☉ 66°NE (T) • 39.613383, -104.617726 ±6 m ▲ 1778 m



State LaPlata
06 Dec 2023, 8:45:44 AM

Exhibit C




☉ 173°S (T) • 39.613392, -104.617727 ±6 m ▲ 1779 m



State LaPlata
06 Dec 2023, 8:45:47 AM

Exhibit D



☉ 195°S (T) • 39.612822, -104.61758 ±6 m ▲ 1782 m



State LaPlata
06 Dec 2023, 8:46:34 AM

Exhibit E



Exhibit F

CA: Failure to control and manage weeds to prevent weed waste and prevent the spread of seeds onto adjacent lands. Comply with Rule 606.c.

CA Resolution: Weeds have been removed to comply with Rule 606.c.