

Inspection Photos

12/05/2023

Operator: NONSUCH NATURAL GAS INC
#10163

Location ID: 324169

Inspection Doc: 696205434

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location ID: 324169



Photo 1: Photos 1-2 taken from southern working pad surface. Photos provide an overview of the Location from north, east to southeast.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location ID: 324169



December 5, 2023

Photo 2: See comments under photo 2.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location ID: 324169



Photo 3: Photos taken from along the access road. Limited inspection due to snow cover, however, unable to find evidence that stormwater and erosion control measures to stabilize, minimize erosion, manage runoff have been implemented. Boulders have been placed along sections of the road. Operator's email communication to staff indicated that that the access road will be reconstructed to redirect runoff, and that a water bar (berm) will be installed across the entrance to limit runoff from Trail Ridge Road; unable to find evidence that this work has been performed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location ID: 324169



Photo 4: Wildlife protection devices (netting) has been maintained.

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location ID: 324169



Photo 5: Caps/plugs missing from tanks.

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location ID: 324169



Photo 6: Limited reclamation inspection due to snow cover, however, unable to find evidence that additional reclamation/revegetation work was performed and control measures to stabilize the seeded soils installed per the corrective actions; areas of the Location that were observable remains predominantly bare.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location ID: 324169



Photo 7: Photo taken from the pit. Gate/Fence has been repaired. Netting remains stored on the east end of the pit.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location ID: 324169



December 5, 2023



39.51505776N 108.20015952W
December 5, 2023

Photo 8: Photos examples showing Undesirable and noxious weeds observed in the previous inspection(s) throughout the Location and interim areas (houndstongue, mullein) were evident above the snow, have matured and produced seed. Ongoing weed management has not been performed, or remains inadequate to keep Location free of undesirable and noxious plant species.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources