

Operator: BONANZA CREEK ENERGY OPERATING

Location Name: Pronghorn B-24 Pad

Loc ID: 437037

Inspection: 696305464



Exhibit A



Exhibit B

CA: Tumbleweed Debris at Pipe Rack. Comply with Rule 606.

CA Resolution: Tumbleweeds have been removed to comply with Rule 606.