

Final Reclamation Inspection

December 5th, 2023

Operator: Simcoe LLC - 10749

Location ID: 334326

Inspection Document #: 714000188

La Plata County, CO

Township: SWNW 21 34N 9W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
 Location Name: Simon Land and Cattle 21U-1R 2, 4
 Location ID: 334326



12/5/23
 +37.180059,-107.837472
 101° E



Photo 1. View of the project area taken from the entrance facing center.

Inspection Photos

Location Name: Simon Land and Cattle 21U-1R 2, 4

Location ID: 334326



Photo 2. Musk thistle and common mullein observed in the interim reclamation areas.