

Final Reclamation Inspection

December 5th, 2023

Operator: Simcoe LLC - 10749

Location ID: 306820

Inspection Document #: 714000194

La Plata County, CO

Township: SESW 27 34N 9W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Simon Land and Cattle 27-01 2
Location ID: 306820



12/5/23
+37.158695,-107.821425
356° N



12/5/23
+37.157542,-107.817348
288° W

Photo 1. View of the project area taken from the entrance facing center.
Note: location sign is damaged and covered with dirt.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-08840

Inspection Photos
Location Name: Simon Land and Cattle 27-01 2
Location ID: 306820



Photo 2. View of eastern interim reclamation area. Vegetation was not fully assessed due to snowy conditions.

