

# Final Reclamation Inspection

December 5th, 2023

Operator: Simcoe LLC - 10749

Location ID: 333450

Inspection Document #: 714000196

La Plata County, CO

Township: NWNE 27 34N 9W M

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Francis White A2, A4  
Location ID: 333450



12/5/23  
+37.165779,-107.809408  
354° N



Photo 1. View of the project area taken from the entrance facing center.



Inspection Photos  
Location Name: Francis White A2, A4  
Location ID: 333450



**Photo 2.** Weedy debris observed in the eastern interim reclamation area.

Inspection Photos  
Location Name: Francis White A2, A4  
Location ID: 333450



12/5/23  
+37.165820,-107.809622  
201° S

**Photo 3.** Gravel pile observed on the southern edge of the disturbance.  
This is considered debris and needs to be removed.

Inspection Photos  
Location Name: Francis White A2, A4  
Location ID: 333450



**Photo 3.** View of surface owner equipment that is stored on the location.

Inspection Photos

Location Name: Francis White A2, A4

Location ID: 333450



**Photo 5.** View of surface owner equipment and debris stored on the northern and western interim reclamation areas. Equipment is interfering with interim reclamation vegetation establishment.