

# Final Reclamation Inspection

December 5th, 2023

Operator: Simcoe LLC - 10749

Location ID: 325794

Inspection Document #: 714000197

La Plata County, CO

Township: NWSE 22 34N 9W M

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Roger Kelly 1  
Location ID: 325794



12/5/23  
+37.173630,-107.809261  
306° NW



Photo 1. View of the project area taken from the entrance facing center.



Inspection Photos  
Location Name: Roger Kelly 1  
Location ID: 325794

12/5/23  
+37.173941,-107.809318  
317° NW



**Photo 2.** Piles of gravel observed on the northern edge of the disturbance. This is considered debris and needs to be removed.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #:067-05515

Inspection Photos  
Location Name: Roger Kelly 1  
Location ID: 325794



12/5/23  
+37.165820,-107.809622  
201° S

**Photo 3.** Gravel pile observed on the southern edge of the disturbance.  
This is considered debris and needs to be removed.



Inspection Photos  
Location Name: Roger Kelly 1  
Location ID: 325794



**Photo 3.** Musk thistle observed in the southern and western interim reclamation areas.

Inspection Photos  
Location Name: Roger Kelly 1  
Location ID: 325794



Photo 5. Musk thistle observed along the access road.

Inspection Photos  
Location Name: Roger Kelly 1  
Location ID: 325794



**Photo 6.** Reference area comprised of smooth brome, crested wheatgrass and kochia.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #:067-05515