

**Operator: BONANZA CREEK ENERGY OPERATING**

**Location Name: State Antelope 31-11HZ**

**Loc ID: 423035**

**Inspection: 696305471**



**Exhibit A**

**CA:** Stained Soil at Gas Engine. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e."

**CA Resolution:** All valves, pipes, fittings, and Production Facilities have been securely fastened per Rule 608.e. Oily Waste has been disposed of in compliance with Rule 905.e.