

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N PARACHUTE/WF15A-23 F23596

Location ID: 335667

Date: 12/4/2023



Location Entrance – Photo #07906



Wellheads – Photo #07917

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N PARACHUTE/WF15A-23 F23596

Location ID: 335667

Date: 12/4/2023



Separators – Photo #07913



Separators – Photo #07914

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N PARACHUTE/WF15A-23 F23596

Location ID: 335667

Date: 12/4/2023



Tank Battery/No Battery Sign Posted – Photo #07908



Open Hole at Tank Battery – Photo #07910

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N PARACHUTE/WF15A-23 F23596

Location ID: 335667

Date: 12/4/2023



Open Hole at Tank Battery – Photo #07911



Open Trench at Separators – Photo #07915



Inspection Photos

Location Name: CAERUS PICEANCE LLC, N PARACHUTE/WF15A-23 F23596

Location ID: 335667

Date: 12/4/2023



Open Trench at Wellheads – Photo #07918