

# Inspection Photos

Loc: 309391

Operator: OGRIS OPERATING LLC

Inspection Date: 12/5/2023

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing northwest along the main road. The culvert has been cleaned out. This area should also be seeded for stabilization.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:309391 | Date: 12/5/2023

## Inspection Photos



**Photo 2.** Facing south toward the wellsite.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:309391 | Date: 12/5/2023