

Inspection Photos

Loc: 309410

Operator: OGRIS OPERATING LLC

Inspection Date: 12/5/2023

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing west at the main access road. This culvert has been cleaned out and maintained.



Inspection Photos



Photo 2. Facing west along the road. This culvert was repaired but additional cleanout will be needed. Lat/Long:37.14485,-104.03594.



Inspection Photos



Photo 3. Facing northwest toward the wellsite.

