

Inspection Photos

Loc: 309300

Operator: OGRIS OPERATING LLC

Inspection Date: 12/5/2023

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northwest along the main road. This area along the roadside has been repaired and rock check dams have been installed.



Inspection Photos



Photo 2. Facing southeast along the access road toward the wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:309300 | Date: 12/5/2023

Inspection Photos



Photo 3. Facing northwest toward the wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:309300 | Date: 12/5/2023