

Final Reclamation Inspection

November 30th, 2023

Operator: Simcoe LLC - 10749

Location ID: 326208

Inspection Document #: 714000187

La Plata County, CO

Township: NWSW 20 34N 9W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
 Location Name: Arthur Mason A2, A4
 Location ID: 326615



12/5/23
 +37.176377,-107.854993
 199° S



12/5/23
 +37.176295, -107.855135
 271° W

Photo 1. View of the project area taken from the entrance facing center. Note: Area is adjacent to a barn and residential lot. Equipment stored on disturbance is not interfering with interim reclamation areas.



Inspection Photos

Location Name: Arthur Mason A2, A4

Location ID: 326615



Photo 2. View of surface owner equipment stored on location.

Inspection Photos
Location Name: Arthur Mason A2, A4
Location ID: 326615

12/5/23
+37.176274,-107.855304
233° SW



Photo 3. View of western interim reclamation area. Vegetation was not fully assessed due to snowy conditions.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #:067-05515