

Inspection Photos

Loc: 308905

Operator: OGRIS OPERATING LLC

Inspection Date: 12/5/2023

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast along the access road which is graded and maintained.



Inspection Photos



Photo 2. Facing east toward the wellsite.



Inspection Photos



Photo 3. Facing northeast toward the reclaimed portion of the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:308905 | Date: 12/5/2023