

Inspection Photos
Location Name: Carl A Miller B 1
Location ID: 317691



Photo 1 well head and equipment



Photo 2 electrical equipment

Inspection Photos
Location Name: Carl A Miller B 1
Location ID: 317691



Photo 3 valve manifold



Photo 4 production equipment

Inspection Photos
Location Name: Carl A Miller B 1
Location ID: 317691




Photo 5 tank battery



Photo 6 tank battery and equipment