

Inspection Photos
Location Name: State Pronghorn J-1 PAD
Location ID: 440840



Energy and Carbon Management Commission
40.42298, -104.27525, 4607.5ft
12/05/2023 14:16:43

Photo 1 – Sign at Entrance



Energy and Carbon Management Commission
40.42392, -104.27565, 4653.5ft
12/05/2023 14:13:57

Photo 2 – Wellheads



Inspection Photos
Location Name: State Pronghorn J-1 PAD
Location ID: 440840




Photo 3 – Risers not OOSLAT at Tank Riser



Photo 4 – Instrumental Air Unit

Inspection Photos
Location Name: State Pronghorn J-1 PAD
Location ID: 440840



Photo 5 – Located Tags



Photo 6 – Separators

Inspection Photos
Location Name: State Pronghorn J-1 PAD
Location ID: 440840



Photo 7 – Locate Tags on Location



Photo 8 – Maintenance Tank

Inspection Photos
Location Name: State Pronghorn J-1 PAD
Location ID: 440840



Photo 9 – Unused Chemical Tank and Tumbleweed Debris



Photo 10 – Gas Lift Injection Meter house