

Inspection Photos
Location Name: State Pronghorn J-12 PAD
Location ID: 431415



Photo 1 – Gas Meter House



Photo 2 – Compressor

Inspection Photos
Location Name: State Pronghorn J-12 PAD
Location ID: 431415



Photo 3 – Compressor



Photo 4 – Separators

Inspection Photos
Location Name: State Pronghorn J-12 PAD
Location ID: 431415



Photo 5 – Middle Separator open to Atmosphere



Photo 6 – ECDs

Inspection Photos
Location Name: State Pronghorn J-12 PAD
Location ID: 431415



Photo 7 – Tank Battery



Photo 8 – Tank Battery Signs

Inspection Photos
Location Name: State Pronghorn J-12 PAD
Location ID: 431415



Photo 9 – Tank Battery – Back side of Tanks



Photo 10 – Wellheads



Inspection Photos
Location Name: State Pronghorn J-12 PAD
Location ID: 431415



Energy and Carbon Management Commission
40.4083, -104.27596, 4525.1ft
12/05/2023 14:37:55

Photo 11 – Gas Lift Injection Meter House



Energy and Carbon Management Commission
40.40737, -104.27589, 4494.6ft
12/05/2023 14:38:25

Photo 12 – Signs at Entrance