

# Inspection Photos

12/05/2023

**Operator:** CAERUS PICEANCE LLC #10456

**Location ID:** 335527

**Inspection Doc:** 696205446

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335527



**Photo 1:** Photos 1-2 taken from the north end of the WPS. Photos provide an overview of the Location from east, south to west.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335527



39.50670636N 108.17674477W  
December 5, 2023

**Photo 2:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 335527



**Photo 3:** Signage pursuant to 605.e not posted at battery.

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335527



December 5, 2023



39.50682629N 108.17686789W  
December 5, 2023

**Photo 4:** Photos show barbed wire on the southwest and northwest edges of the working pad surface.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335527



**Photo 5:** Unused equipment.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources