

Inspection Photos

12/05/2023

Operator: CAERUS PICEANCE LLC #10456

Location ID: 324389

Inspection Doc: 696205452

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 324389



Photo 1: Photos 1-2 taken from the southeast end end of the WPS. Photos provide an overview of the Location from northeast, east, south, to southwest.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 324389



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 324389



Photo 3: Loadline not capped/plugged at produced water tank; honeypot open. Capacity information no apparent at condensate tank.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 324389



Photo 4: Fence in disrepair.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 324389



Photo 5: Wellhead.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources