

Inspection Photos

12/05/2023

Operator: CAERUS PICEANCE LLC #10456

Location ID: 324388

Inspection Doc: 696205454

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 324388



Photo 1: Photos taken from the north end end of the WPS. Photos provide an overview of the Location from southeast to southwest.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 324388



Photo 2: Tank loadline not capped/plugged.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 324388



December 5, 2023

Photo 3: Fence in disrepair.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 324388



December 5, 2023

Photo 4: Trash/debris.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 324388



Photo 5: Wellhead.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources