

Inspection Photos

12/05/2023

Operator: CAERUS PICEANCE LLC #10456

Location ID: 324170

Inspection Doc: 696205456

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 324170



Photo 1: Photos 1-2 taken from the west end end of the WPS. Photos provide an overview of the Location from north, northeast, southeast to south.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 324170



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 324170



Photo 3: Tank loadline not capped/plugged.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 324170



Photo 4: Fence in disrepair.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources