

Inspection Photos
Location Name: State Pronghorn 11-14-1HZ
Location ID: 420123



Photo 1 – Pumping Unit



Photo 2 – Wellhead

Inspection Photos
Location Name: State Pronghorn 11-14-1HZ
Location ID: 420123



Photo 3 – 2" Riser not marked with OOSLAT



Photo 4 – Tank Battery

Inspection Photos
Location Name: State Pronghorn 11-14-1HZ
Location ID: 420123



Photo 5 – Produces Water Tank Labels faded no longer visible



Photo 6 – Produces Water Tank Labels faded no longer visible

Inspection Photos

Location Name: State Pronghorn 11-14-1HZ

Location ID: 420123



Photo 7 – Tank Battery Sign




Photo 8 – Tank Battery Sign



Inspection Photos
Location Name: State Pronghorn 11-14-1HZ
Location ID: 420123



Photo 9 – Separators and ECD




Photo 10 – 1" Risers not marked with OOSLAT