

Inspection Photos
Location Name: State Pronghorn 11-2HZ
Location ID: 422681



Energy and Carbon Management Commission
40.43591, 104.29805, 4591.5ft
12/05/2023 15:31:13

Photo 1 – Tank Battery Signs



Energy and Carbon Management Commission
40.43586, 104.29794, 4598.1ft
12/05/2023 15:31:33

Photo 2 – Water Tank Labels have been installed

Inspection Photos
Location Name: State Pronghorn 11-2HZ
Location ID: 422681



Photo 3 – Separators



Photo 4 – Wellhead



Inspection Photos
Location Name: State Pronghorn 11-14-1HZ
Location ID: 420123




Photo 5 – 2" Riser not marked with OOSLAT