

Inspection Photos
Location Name: HOWARD USX A-66N64W/9NWSE
Location #: 306349



Colorado Energy & Carbon Management Commission
Weld County
+40.498945,-104.552784
176° S
2023-12-05 14:12

Photo #1

Howard USX A 9-10(123-24495) Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: Cement-squeeze



Colorado Energy & Carbon Management Commission
Weld County
+40.498819,-104.552297
282° W
2023-12-05 14:19

Photo #2

Howard USX A 9-10 Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: Cement-squeeze
Site safety signage



Inspection Photos
Location Name: HOWARD USX A-66N64W/9NWSE
Location #: 306349



Colorado Energy & Carbon Management Commission
 Weld County
 +40.496637 -104.545852
 356° N
 2023-12-05 14:30

Photo #3
Howard USX A 9-10 Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: Cement-squeeze
Wellsite entrance



Colorado Energy & Carbon Management Commission
 Weld County
 +40.498805 -104.55142
 185° S
 2023-12-05 14:10

Photo #4
Howard USX A 9-10 Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: Cement-squeeze
JSA: 2023-12-05



Inspection Photos

Location Name: HOWARD USX A-66N64W/9NWSE

Location #: 306349



Photo #5

Howard USX A 9-10 Battery site

Plugged & Abandoned | PA

Plugging Ops; Cementing: Cement-squeeze

Battery sign



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources