

# Inspection Photos

Location Name: HOWARD USX A-66N64W/9NWSE

Location #: 306349



Colorado Energy & Carbon Management Commission  
Weld County  
+40.498829 -104.553195  
114° SE  
2023-12-06 09:30

**Photo #1**

**Howard USX A 9-10(123-24495) Wellsite**

**Plugged & Abandoned | PA**

**Plugging Ops; Cementing: Cement to surface**



Colorado Energy & Carbon Management Commission  
Weld County  
+40.4988191 -104.552297  
282° W  
2023-12-05 14:19

**Photo #2**

**Howard USX A 9-10 Wellsite**

**Plugged & Abandoned | PA**

**Plugging Ops; Cementing: Cement to surface**

*Site safety signage*

*prior photo*



**COLORADO**


**Energy & Carbon Management  
Commission**

Department of Natural Resources

**Inspection Photos**  
**Location Name: HOWARD USX A-66N64W/9NWSE**  
**Location #: 306349**



Colorado Energy & Carbon Management Commission  
 Weld County  
 +40.496637 - 104.545852  
 356° N  
 2023-12-05 14:30



Colorado Energy & Carbon Management Commission  
 Weld County  
 +40.498847 - 104.552325  
 69° E  
 2023-12-06 10:22

**Photo #3**  
**Howard USX A 9-10 Wellsite**  
**Plugged & Abandoned | PA**  
**Plugging Ops; Cementing: Cement to surface**  
*Wellsite entrance*  
*prior photo*

**Photo #4**  
**Howard USX A 9-10 Wellsite**  
**Plugged & Abandoned | PA**  
**Plugging Ops; Cementing: Cement to surface**  
**JSA: 2023-12-06**



## Inspection Photos

Location Name: HOWARD USX A-66N64W/9NWSE

Location #: 306349



### Photo #5

Howard USX A 9-10 Battery site

Plugged & Abandoned | PA

Plugging Ops; Cementing: Cement to surface

*Battery sign*

*prior photo*



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources