

Inspection Photos

Location Name: CAERUS PICEANCE LLC, Federal/PE-25

Location ID: 423081

Date: 12/6/2023



Location Entrance – Photo #07927



NW Corner of Location – Photo #07928

Inspection Photos

Location Name: CAERUS PICEANCE LLC, Federal/PE-25

Location ID: 423081

Date: 12/6/2023



Wellheads – Photo #07931



Separators – Photo #07932

Inspection Photos

Location Name: CAERUS PICEANCE LLC, Federal/PE-25

Location ID: 423081

Date: 12/6/2023



Tank Battery – Photo #07934



Debris Near Wellhead – Photo #07930