

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/26NENE

Location ID: 335042

Date: 12/6/2023



Location Entrance – Photo #07937



Location Entrance – Photo #07941

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/26NENE

Location ID: 335042

Date: 12/6/2023



Wellheads – Photo #07938



Separators – Photo #07942

Date: 12/6/2023



Lack of Stabilization – Photo #07945

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/26NENE

Location ID: 335042

Date: 12/6/2023



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #07946