

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SPECIALTY RESTAURANTS-67S96W/26SWNW

Location ID: 334702

Date: 12/6/2023



Dec 6, 2023 at 10:17:39  
Parachute CO 81635  
United States



Dec 6, 2023 at 10:18:03  
Parachute CO 81635  
United States

Location Entrance – Photo #07959

Wellheads – Photo #07960

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SPECIALTY RESTAURANTS-67S96W/26SWNW

Location ID: 334702

Date: 12/6/2023



Dec 6, 2023 at 10:18:33  
Parachute CO 81635  
United States

Separators – Photo #07962



Dec 6, 2023 at 10:18:49  
Parachute CO 81635  
United States

Tank Battery – Photo #07963



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SPECIALTY RESTAURANTS-67S96W/26SWNW

Location ID: 334702

Date: 12/6/2023



**Insufficient Erosion Control – Photo #07964**