

STATE OF COLORADO
OIL AND GAS CONSERVATION COMMISSION
DEPARTMENT OF NATURAL RESOURCES

SUBMIT ORIGINAL AND 1 COPY



FOR OFFICE USE ONLY			
<input checked="" type="checkbox"/> ET	<input type="checkbox"/> FE	<input type="checkbox"/> UC	<input type="checkbox"/> SE

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

<input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> COALBED METHANE <input type="checkbox"/> INJECTION WELL <input checked="" type="checkbox"/> OTHER P&A'd well			5 FEDERAL INDIAN OR STATE LEASE NO
2 NAME OF OPERATOR Phillips Petroleum Company			6 PERMIT NO
3 ADDRESS OF OPERATOR P. O. Box 1967 ATTN: J.F. MITCHELL			7 API NO 05-103-05262
CITY Houston	STATE TX	ZIP CODE 77251-1967	8 WELL NAME Mannel
4 LOCATION OF WELL (Report location clearly and in accordance with any State requirements See also space 17 below) At surface 1980' FNL & 1980' FEL At proposed prod zone			9 WELL NUMBER 2
12 COUNTY Rio Blanco			10 FIELD OR WILDCAT Powell Park
			11 QTR. QTR. SEC. T.R. AND MERIDIAN SE NE Sec 26-T1N-R95W



Check Appropriate Box To Indicate Nature of Notice, Report or Notification

13A NOTICE OF INTENTION TO: <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/> COMMINGLE ZONES <input type="checkbox"/> FRACTURE TREAT <input type="checkbox"/> REPAIR WELL <input checked="" type="checkbox"/> OTHER <u>re-abandon</u>	13B. SUBSEQUENT REPORT OF: <input type="checkbox"/> FINAL PLUG AND ABANDONMENT (SUBMIT 3RD PARTY CEMENT VERIFICATION AND JOB LOG) <input type="checkbox"/> ABANDONED LOCATION (WELL NEVER DRILLED - SITE MUST BE RESTORED WITHIN 6 MONTHS) <input type="checkbox"/> REPAIRED WELL <input type="checkbox"/> OTHER <small>*Use Form 5 - Well Completion or Recompletion Report and Log for subsequent report of Multiple/Commingled Completions and Recompletions</small>	13C. NOTIFICATION OF: <input type="checkbox"/> SHUT-IN TEMPORARILY ABANDONED (DATE _____) (REQUIRED EVERY 6 MONTHS) <input type="checkbox"/> PRODUCTION RESUMED (DATE _____) <input type="checkbox"/> LOCATION CHANGE (SUBMIT NEW PLAT) <input type="checkbox"/> WELL NAME CHANGE <input type="checkbox"/> OTHER _____
--	--	---

14 DESCRIBE PROPOSED OR COMPLETED OPERATIONS ON THIS FORM (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent

15 DATE OF WORK Start approx July 10, 1995

Well was drilled in 1958 and P&A'd as a dry hole (see attached schematic). Due to reports of hearing gas bubbling inside dry hole marker, Phillips requests approval to investigate and possibly re-abandon to correct this problem. A procedure can not be established as well conditions are not known at this time.




16. I hereby certify that the foregoing is true and correct

SIGNED Jacob Mitchell TELEPHONE NO. (713) 669-3509
NAME (PRINT) Jacob F. Mitchell TITLE Director, Regulatory/Compliance DATE 5/1/95

(This space for Federal or State office use)

APPROVED [Signature] TITLE SR. PETROLEUM ENGINEER O & G Cons. Comm. DATE 5/19/95

CONDITIONS OF APPROVAL, IF ANY:
call Jaime Adkins @ 970-858-7521 before attempting work



10 5x Surf Plug - INST. DM MARKER

28'-58' 10 5x CMT Plug.

DRL 8 3/4" HOLE ^{510'} → REAMED TO 13 3/4" TO 452'


441' 8 5/8" 24# J-55

CMT w/ 365 SX GOOD RETURNS.

TESTED C/L TO 600 PSI OK PRIOR TO DRILL OUT.

367'-470' 35 SX CMT Plug.

1750'-1850' 50 SX CMT Plug



DRL 7 7/8" HOLE.

4270-4420 50 SX CMT Plug.

4420' OH TD

200 SHEETS EYE CASE 5 SQUARE
100 RECYCLED WHITE 5 SQUARE
45 50% RECYCLED WHITE 5 SQUARE
MADE IN U.S.A.

National Brand