

# Interim Reclamation and Stormwater Inspection

Date: 12/06/2023

Operator: NOBLE ENERGY INC - 100322

Location ID: 432532

Inspection Document #: 708200745

Weld County, CO

Dylan Edwardson  
Reclamation Specialist, ECMC



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: LC24-01 Pad  
Location ID: 432532



**Photo 1.** Unused equipment (hard line) observed near wellheads.

Inspection Photos  
Location Name: LC24-01 Pad  
Location ID: 432532



**Photos 2 & 3.** Northern interim areas. Appears interim reclamation activities have been performed to reduce disturbance areas only needed for production operations. Vegetation throughout the interim areas is progressing towards Rule 1003 standards and will need to be re-inspected during the next growing season to verify vegetative compliance; therefore, the location will remain IN-PROCESS. Operator shall continue to monitor and manage this site until the location meets Rule 1003 standards, including stormwater and weed management.

Inspection Photos  
Location Name: LC24-01 Pad  
Location ID: 432532



**Photos 4 & 5.** Eastern interim areas; see comments in Photos 2 & 3.

Inspection Photos  
Location Name: LC24-01 Pad  
Location ID: 432532



**Photo 6 & 7.** Southern interim areas; see comments in Photos 2 & 3.

Inspection Photos  
Location Name: LC24-01 Pad  
Location ID: 432532



**Photos 8 & 9.** Western interim areas; see comments in Photos 2 & 3.