

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, PARACHUTE RANCH FEDERAL-67S96W/35NESE

Location ID: 334376

Date: 12/6/2023



Location Entrance – Photo #07991



NW Corner of Location – Photo #07992

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, PARACHUTE RANCH FEDERAL-67S96W/35NESE

Location ID: 334376

Date: 12/6/2023



Wellheads – Photo #07993



Separators – Photo #07997



## Inspection Photos

Location Name: CAERUS PICEANCE LLC, PARACHUTE RANCH FEDERAL-67S96W/35NESE

Location ID: 334376

Date: 12/6/2023



Tank Battery – Photo #07996



Lack of Stabilization – Photo #07995

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, PARACHUTE RANCH FEDERAL-67S96W/35NESE

Location ID: 334376

Date: 12/6/2023



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit**  
– Photo #07998