

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-12 Pad

Location ID: 334710



Photo # 8518 From entrance to location



Photo # 8519 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-12 Pad

Location ID: 334710



Photo # 8520 Location



Photo # 8521 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-12 Pad

Location ID: 334710



Dec 6, 2023 at 9:53:34 AM
CO

Photo # 8522 Location



Dec 6, 2023 at 9:58:12 AM
CO

Photo # 8523 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-12 Pad

Location ID: 334710



Photo # 8524 Location



Photo # 8525 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-12 Pad

Location ID: 334710



Photo # 8526 Stained gravel



Photo # 8527 Stained gravel

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-12 Pad

Location ID: 334710



Photo # 8528 Stained gravel



Photo # 8529 Stained gravel

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-12 Pad

Location ID: 334710



Photo # 8530 Stained gravel