

Inspection Photos

Location Name: CAERUS PICEANCE LLC Battlement Mesa 35C-795 Pad

Location ID: 334087



Photo # 8806 From entrance to location




Photo # 8807 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC Battlement Mesa 35C-795 Pad

Location ID: 334087



Photo # 8808 Location



Photo # 8809 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC Battlement Mesa 35C-795 Pad

Location ID: 334087



Photo # 8810 Location



Photo # 8811 Methanol tank label weathered & illegible/
tank improperly labeled/lacks required information (near
wellheads)

Inspection Photos

Location Name: CAERUS PICEANCE LLC Battlement Mesa 35C-795 Pad

Location ID: 334087



**Photo # 8812 Methanol tank label weathered & illegible/
tank improperly labeled/lacks required information (near
wellheads)**



Photo # 8813 Methanol tank (near wellheads)

Inspection Photos

Location Name: CAERUS PICEANCE LLC Battlement Mesa 35C-795 Pad

Location ID: 334087



Photo # 8814 Methanol tank improperly labeled/lacks required information (next to production separators)



Photo # 8815 Methanol tank (next to production separators)

