

Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 35L-795 Pad

Location ID: 416986



Photo # 8830 From entrance to location



Photo # 8831 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 35L-795 Pad

Location ID: 416986



Photo # 8832 Location



Photo # 8833 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 35L-795 Pad

Location ID: 416986



Photo # 8834 Location



Photo # 8835 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 35L-795 Pad

Location ID: 416986



Photo # 8836 Location



Photo # 8837 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 35L-795 Pad

Location ID: 416986



Photo # 8838 Location



Photo # 8839 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 35L-795 Pad

Location ID: 416986



Photo # 8840 Unused equipment



Photo # 8841 Wellhead lacks signage

Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 35L-795 Pad

Location ID: 416986




Photo # 8842 Wellhead lacks signage



Photo # 8843 Unused equipment & staining in secondary containment

Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 35L-795 Pad

Location ID: 416986



Photo # 8844 Staining in secondary containment



Photo # 8845 Staining in secondary containment

Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 35L-795 Pad

Location ID: 416986




Photo # 8846 Unused equipment & staining in secondary containment



Photo # 8847 Methanol tank improperly labeled/labeled with inaccurate information/lacks required information

Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 35L-795 Pad

Location ID: 416986



Photo # 8848 Methanol tank improperly labeled/labeled with inaccurate information/lacks required information



Photo # 8849 Tank label weathered & illegible

Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 35L-795 Pad

Location ID: 416986



Photo # 8850 Methanol tank improperly labeled/labeled with inaccurate information/lacks required information