

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Location Name: PRONGHORN-65N61W 4NWNE

Loc ID: 306061

Inspection: 713900047



Exhibit A



Exhibit B



Exhibit C



Exhibit D

CA: This location does not comply with Rule 1004. Reclamation rules require reclamation activities to be conducted within twelve months of plugging on non-cropland. Well was plugged 12/05/2018. It does not appear reclamation work has been successful; gravel remains throughout the location; weedy, annual vegetation was observed which includes but not limited to cereal rye, Russian thistle and lovegrass. Comply with Rule 1004. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.

CA Resolution: Operator has reported that the location has been mowed, recontoured, and reseeded to comply with Rule 1004 regarding reclamation.