



**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

<b>Emergency Contact Number:</b>			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:	Calibration 4-2023		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		40.185990,-104.757890
Comment:					
Corrective Action:		Date:			

<u>Paint</u>				
Condition				
Other (Content)				
Other (Capacity)				
Other (Type)				

<u>Berms</u>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		40.185990,-104.757890
Comment:					
Corrective Action:					Date:

<u>Paint</u>				
Condition	Adequate			
Other (Content)				
Other (Capacity)				
Other (Type)				

<u>Berms</u>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		40.186310,-104.758540
Comment:					
Corrective Action:					Date:

<u>Paint</u>				
Condition				
Other (Content)				
Other (Capacity)	150 Bbl			
Other (Type)				

<u>Berms</u>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shared with condensate.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLS	STEEL AST		40.186310,-104.758540

Comment:		
Corrective Action:		Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type	Ignitor/Combustor	
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 482248 Type: TANK API Number: - Status: AC Insp. Status: AO

**COGCC Comments**

Comment	User	Date
<a href="#">Routine battery inspeciton.</a>	carlilec	12/11/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690011977	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6351895">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6351895</a>