

Inspection Photos

Loc: 321092

Operator: INVESTMENT EQUIPMENT LLC

Inspection Date: 12/6/2023

County: BACA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast at the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:321092 | Date: 12/6/2023

Inspection Photos



Photo 2. Facing northeast at the location. The dark brown vegetation is undesirable weed that need to be controlled.

