

Inspection Photos

Loc: 321096

Operator: INVESTMENT EQUIPMENT LLC

Inspection Date: 12/6/2023

County: BACA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast along the access road. This area has not revegetated.



Inspection Photos



Photo 2. Facing back southwest along the access road. This area has not revegetated



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:321096 | Date: 12/6/2023

Inspection Photos



Photo 2. Facing northeast at the location. Perennial vegetation is progressing at the location.



Inspection Photos



Photo 2. Facing northwest at the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:321096 | Date: 12/6/2023

Inspection Photos



Photo 5. Facing west at the location.



Inspection Photos



Photo 6. Facing east at the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:321096 | Date: 12/6/2023

Inspection Photos



Photo 7. East side of the location facing northwest.

