

Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 34F-795 Pad

Location ID: 334384



Photo # 8911 From entrance to location



Photo # 8912 From entrance to location

Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 34F-795 Pad

Location ID: 334384




Photo # 8913 Location

Photo # 8914 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 34F-795 Pad

Location ID: 334384



Photo # 8915 Location



Photo # 8916 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 34F-795 Pad

Location ID: 334384



Photo # 8917 Tank labeled damaged & missing required information

Photo # 8918 Open ended piping/wildlife hazards

Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 34F-795 Pad

Location ID: 334384



Photo # 8919 Open ended piping/wildlife hazard



Photo # 8920 Open ended piping/wildlife hazard

Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 34F-795 Pad

Location ID: 334384



Dec 7, 2023 at 1:42:00 PM



Dec 7, 2023 at 1:42:03 PM

Photo # 8921 Debris

Photo # 8922 Debris

Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 34F-795 Pad

Location ID: 334384



Photo # 8923 Wellhead lacks signage



Photo # 8924 Wellhead lacks signage

Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 34F-795 Pad

Location ID: 334384



Photo # 8925 Unused equipment

