

Inspection Photos
Location Name: Park 4-63-4 NE Well Pad
Location ID: 459857



December 11, 2023 at 9:52 AM
+40.3430, -104.4339
110° E

Weld County
Energy & Carbon Management Commission

Location

Inspection Photos
Location Name: Park 4-63-4 NE Well Pad
Location ID: 459857



Pig Station

Pit needs berms/ capacity sign/ NFPA placard and pigging waste removed.