

# Inspection Photos

Location Name: Park 4-63-4 NE Production Facility  
Location ID: 459857



**Location Sign**

**Trash "Hose"**

# Inspection Photos

Location Name: Park 4-63-4 NE Production Facility

Location ID: 459857



**Location**

**Equipment**

# Inspection Photos

Location Name: Park 4-63-4 NE Production Facility

Location ID: 459857



**Production Tanks**

**Equipment**

**Inspection Photos**  
**Location Name: Park 4-63-4 NE Production Facility**  
**Location ID: 459857**




**Mechanical Condtns**

**Stained Soil**

## Inspection Photos

Location Name: Park 4-63-4 NE Production Facility

Location ID: 459857



**Unmarked risers need to be marked by identifying what they are and tagged with OOSLAT. "LOTO"**

**Unmarked risers need to be marked by identifying what they are and tagged with OOSLAT. "LOTO"**